


10/031852

GENERAL

MATERIALS

1/71


Fig. 1



107031852

2/71

Fig. 2



10/031852

3/71





Fig. 3

10/031852

4/71

Fig. 4



10031852-042402

0,031852

5/71




Fig.5

100-215 " 01242

10/031852

SIMONAL AS 3.1739038162

6/71

Fig. 6






Fig. 7



10/031852


7/71

Fig. 8



10024852-01245

8/71


*Fig.9*

10934652 \* 042502

10/031852

9/71

Fig. 10



2010070420070007

KODAK SAFETY FILM

10/031852

10/71





Fig. 11

10/031852

01031852

11/71

Fig.12



10/031852

12/71




Fig. 13

10/031852

13/71

Fig. 14





Fig. 15




10/031852

231 REG, #660

14/71

Fig. 16



10/031852

15/71




Fig. 17

10/031852

16/71





Fig. 18

10/031852

17/71

Fig. 19




10031852-012

1000 W/L 48 0.93 10/031852  
39A TEE

18/71

Fig. 20




1000 W/L 48 0.93 10/031852

10/031852


19/71

Fig. 21



20/71

Fig. 22



10031852 012402

10/031852

21/71





Fig.23

10/031852

22/71

Fig. 24



100031852 "O" 10/031852

23/71




Fig. 25

0/031852

24/71

Fig. 26A






Fig. 26B



10/031852

25/71

Fig. 26C



0/031852

26/71

Fig. 27

SCHEMATIC VIEW OF PRESSURIZING MEMBER	PARAMETER			DECISION			PRINT STATE
	SQ. ANGLE : $\theta$ (deg)	GAP : T (mm)	HEIGHT : S (mm)	SOLDER ROLLING PROPERTY	SOLDER SCRAPING STATE ON MASK		
			1	○	○	○	○
			2	○	○	○	○
			3	○	○	○	○
			5	△	○	○	○
			1	○	○	○	○
			2	○	○	○	○
			3	○	○	○	○
			5	△	○	○	○
			1	○	○	○	○
			2	○	○	○	○
			3	○	○	○	○
			60	○	○	○	○
			1	○	○	○	○
			2	○	○	○	○
			3	○	○	○	○
			5	△	○	○	○
			3	○	○	○	○
			2	○	○	○	○
			3	○	○	○	○
			5	△	○	○	○

2003 MAR 4 8

031852  
031035R FEB

27/71

Fig.28A






Fig.28B



10/031852

28/71

Fig.29



10/031852

29/71


Fig. 30

10/031852

30/71

Fig. 31


Fig. 32



10/031852

32/71

Fig. 33




10031852-01240

10/031852

33/71

Fig. 34



10/031852

34/71





Fig.35


Fig. 36



10/031852

36/71

Fig. 37



37/71

Fig.38A




Fig.38B




Fig.39

10031852 042442






Fig.40



10/031852


40/71

Fig.41




10/031852

41/71



10/031852

42/71



REG KALAS 3/03/1852

43/71




Fig. 44

10/031852

44/7.1




Fig. 45

10/031852

45/71

Fig. 46




Fig. 47A






Fig. 47B



100031852 100031852 100031852

47/71

Fig.48



10/031852

48/71

Fig. 49






Fig. 50




50/71

Fig.51



51/71


Fig. 52



10/031852

52/71


Fig. 53



10/031852

53/71

Fig. 54




10/031852

10/031852

54/71


Fig. 55



1004952-02400

55/71


Fig. 56



10/031852


56/71

Fig. 57




100-2486-01-000

Fig. 58



100-41852-942402


Fig. 59



0004552-024202


Fig.60

59/71



60/71

Fig.61



10/031852

Fig. 62A




Fig. 62B




Fig. 62C





Fig. 62D



10031852 62A-D

20180310-A581E00T

10/031852

62/71

Fig. 63A






Fig. 63B



2005 MAR 4 S 101035N 1031852

63/71

Fig. 64



10/031852

64/71

Fig. 65A





Fig. 65B



10/031852

65/71




Fig. 66

66/71

Fig. 67A




Fig. 67B




Fig. 67C





Fig. 67D



2005 MAC & S 10/10/31852

67/71




Fig. 68

10/031852

68/71




Fig. 69

69/71

Fig. 70A




Fig. 70B





Fig. 71



204200-268700T

10/031052

70/71




Fig. 72

30743-A  
197309162

71/71

Fig. 73A




Fig. 73B




Fig. 73C




Fig. 73D




Fig. 73E

